



Dual & differential input

MANOMETER




TABLE OF CONTENTS

1. FEATURES.....	1
2. SPECIFICATIONS.....	1
2-1 General Specifications.....	1
2-2 Electrical Specifications.....	3
3. FRONT PANEL DESCRIPTION.....	4
3-1 Display.....	4
3-2 Power Off/On Button.....	4
3-3 Hold Button	4
3-4 Zero Button	4
3-5 " MAX./MIN. " Button.....	4
3-6 Unit Button.	4
3-7 P1 input sockets.....	4
3-8 P2 input socket.....	4
3-9 Battery Compartment/Cover.....	4
3-10 PLug/quick coupler.....	4
4. MEASURING PROCEDURE.....	5
5. AUTO POWER OFF DISABLE.....	6
6. BATTERY REPLACEMENT.....	7

1. FEATURES

- * Dual & differential input, \pm 2000 mbar max. range.
- * Application : Industrial, laboratory, heating, ventilation, medical hospital, used for air or not corrosive and not ionized gas & liquid.
- * Sensor is built inside the housing.
- * Single lugs for pipe connection.
- * 8 kind display units (mbar, psi, Kg/cm², mm Hg, inch Hg, meter H₂O, inch H₂O, Atmosphere) select by push button on the front panel
- * Auto shut off saves battery life.
- * Zero button on the front panel, easy to offset the zero value.
- * Microprocessor circuit assures maximum possible accuracy, provides special functions and features,
- * Super large LCD display with contrast adjustment for best viewing angle.
- * Records maximum & minimum readings with recall.
- * Data Hold function for stored the desired value on display.
- * Built-in low battery indicator.

2. SPECIFICATIONS

2-1 General Specifications

Circuit	Microprocessor LSI circuit.
Display	61 mm x 34 mm super large LCD display. 15 mm (0.6") digit size.

Display units	mbar, psi, Kg/cm ² , mm Hg, inch Hg, meter H ₂ O, inch H ₂ O, Atmosphere.
Function	Dual & differential input, data hold, zero/relative, memory.
Zero adjust	Push button on the front panel.
Sensor	* Sensor is built inside the housing. * Piezoelectric sensor.
	 * Used for air or not corrosive and not ionized gas & liquids.
Data hold	By push button.
Data record	Record maximum & minimum readings.
Sampling time	Approx. 0.8 second.
Power off	Auto shut off, saves battery life or manual off by push button.
Operating temperature	0 to 50 °C (32 to 122 °F).
Operating humidity	Less than 80% R.H.
Power supply	006P DC 9V battery (heavy duty).
Power current	Approx. DC 6.0 mA.
Weight	345 g/0.76 LB .
Dimension	185 x 73 x 38 mm (7.2 x 3.0 x 1.4 inch)
Accessories included	* Instruction manual..... 1 PC. * Hard carrying case..... 1 PC. * PLug for quick coupler..... 2 PCs.

2-2 Electrical Specifications

Unit	Max. range	Resolution
mbar	± 2000 mbar	1 mbar
psi	± 29 psi	0.02 psi
Kg/cm ²	± 2.040 Kg/cm ²	0.001 Kg/cm ²
mm Hg	± 1500 mm Hg	1 mm Hg
inch Hg	± 59.05 inch Hg	0.05 inch Hg
meter H ₂ O	± 20.40 meter H ₂ O	0.01 meter H ₂ O
inch H ₂ O	± 802 inch H ₂ O	0.5 inch H ₂ O
Atmosphere	± 1.974 Atmosphere	0.001 Atmosphere

Unit	Max. range	Accuracy
mbar	± 2000 mbar	$\pm 2\%$ F. S.
psi	± 29 psi	
Kg/cm ²	± 2.040 Kg/cm ²	
mm Hg	± 1500 mm Hg	
inch Hg	± 59.05 inch Hg	
meter H ₂ O	± 20.40 meter H ₂ O	
inch H ₂ O	± 802 inch H ₂ O	
Atmosphere	± 1.974 Atmosphere	

Note :
 * 23 ± 5 °C.
 *F.S. : full scale
 *Included linearity,
 hysteresis and
 repeatability

Remark :

Measuring unit	Display unit
mbar	m Bar
psi	Psi
Kg/cm ²	Kg /cm²
mm Hg	mm /Hg
inch Hg	in/Hg
meter H ₂ O	m H₂O
inch H ₂ O	inch H₂O
Atmosphere	ATP

3. FRONT PANEL DESCRIPTION




Fig. 1

- | | |
|--------------------------|--------------------------|
| 3-1 Display | 3-7 P1 input socket |
| 3-2 Power Off/On Button | 3-8 P2 input socket |
| 3-3 Hold Button | 3-9 Battery Compartment |
| 3-4 Zero Button | /Cover |
| 3-5 " MAX./MIN. " Button | 3-10 PLug/ quick coupler |
| 3-6 Unit Button | |

4. MEASURING PROCEDURE

- 1) Power on the meter by pressing the " Power Off/On Button " (3-2, Fig. 1).
- 2) Select the desired temperature units (mbar, psi, Kg/cm², mm Hg, inch Hg, meter H₂O, inch H₂O, Atmosphere) by pushing the " Unit Button " (3-6, Fig. 1).
- 3) **Zero adjusting**
Adjust the display reading to zero value by pushing the " Zero Button " (3-4, Fig. 1)
- 4) Install the measuring pipe to " Plug/quick coupler " (3-10, Fig. 1).
- 5) The meter is build the two input socket (P1 input socket, P2 input socket) for accepting the differential pressure input.
Connecting the pipe along the " Plug " (3-10, Fig. 1) to
 - a. " *P1 input socket* " (3-7, Fig. 1) only
 - b. " *P2 input socket* " (3-8, Fig. 1) only
 - c. Both *P1 & P2 input socket*

The LCD will show the measuring pressure value.

Note :

- * If the *P1* pressure > *P2* pressure, the display will get positive reading.
- * If the *P1* pressure < *P2* pressure, the display will get negative reading.


- 6) **Data Hold**

- * During the measurement, pressing the " Hold Button " (3-3, Fig. 1) will freeze the measured value & the LCD will show " HOLD " symbol.
- * Press the " Hold Button " again to cancel the data hold function.

7) Data Record (Maximum, Minimum reading)

- * The DATA RECORD function displays the maximum and minimum readings. To start the DATA RECORD function, press the " MAX./MIN. Button " (3-5, Fig. 1) once. " REC " symbol will appear on the LCD display.
- * With the " REC " symbol on the display :
 - (a) Press the " MAX./MIN. Button " (3-5, Fig. 1) once, the " Max " symbol along with the maximum value will appear on the display.
 - (b) Press the " MAX./MIN. Button " again, the " Min " symbol along with the minimum value will appear on the display.
 - (c) To exit the memory record function, press the " MAX./MIN. Button " continuously for at least 2 seconds. The display will revert to the current reading.

8) For quick measurement, follow the procedures shown below :



5. AUTO POWER OFF DISABLE

The instrument has built-in "Auto Power Shut-off" in order to prolong battery life. The meter will switch off automatically if none of the buttons are pressed within 10 min.

To de-activate this feature, Select the memory record function during measurement, by pressing the "MAX./MIN. Button" (3-5, Fig. 1).

6. BATTERY REPLACEMENT

- 1) When the left corner of LCD display show "LBT", it is necessary to replace the battery. However, in-spec measurement may still be made for several hours after low battery indicator appears before the instrument become inaccurate.
- 2) Slide the Battery Cover (3-9, Fig. 1) away from the instrument and remove the battery.
- 3) Install a 9 V battery (PP3 type) and replace the cover.