

omega.com

CEOMEGA".

www.omega.com e-mail: info@omega.com

FL-W7000 Flowmeter



OMEGAnet® On-Line Service www.omega.com

Internet e-mail info@omega.com

Servicing North America:

USA:

One Omega Drive, P.O. Box 4047

ISO 9001 Certified

Stamford CT 06907-0047

TEL: (203) 359-1660

FAX: (203) 359-7700

e-mail: info@omega.com

Canada:

976 Bergar

Laval (Quebec) H7L 5A1

TEL: (514) 856-6928

e-mail: info@omega.ca

FAX: (514) 856-6886

For immediate technical or application assistance:

USA and Canada: Sales Service: 1-800-826-6342 / 1-800-TC-OMEGA® Customer Service: 1-800-622-2378 / 1-800-622-BEST® Engineering Service: 1-800-872-9436 / 1-800-USA-WHEN® . TELEX: 996404 EASYLINK: 62968934 CABLE: OMEGA

Mexico:

TEL: (001) 800-826-6342

En Español: (001) 203-359-7803

FAX: (001) 203-359-7807 e-mail: espanol@omega.com

info@omega.com.mx

Servicing Europe:

Benelux:

Postbus 8034, 1180 LA Amstelveen, The Netherlands

TEL: +31 (0)20 6418405

FAX: +31 (0)20 6434643

Toll Free in Benelux: 0800 0993344

e-mail: nl@omega.com

Czech Republic:

Rudé armády 1868, 733 01 Karviná 8

TEL: +420 (0)69 6311899

FAX: +420 (0)69 6311114

Toll Free: 0800-1-66342

e-mail: czech@omega.com

France:

9, rue Denis Papin, 78190 Trappes

TEL: +33 (0)130 621 400

FAX: +33 (0)130 699 120

Toll Free in France: 0800-4-06342 e-mail: france@omega.com

Germany/Austria: Daimlerstrasse 26, D-75392 Deckenpfronn, Germany

TEL: +49 (0)7056 3017

FAX: +49 (0)7056 8540

Toll Free in Germany: 0800 TC-OMEGA[™]

e-mail: germany@omega.com

United Kingdom:

One Omega Drive, River Bend Technology Centre

ISO 9002 Certified

Northbank, Irlam, Manchester

M44 5EX United Kingdom

FAX: +44 (0)161 777 6622 TEL: +44 (0)161 777 6611

Toll Free in United Kingdom: 0800-488-488

e-mail: sales@omega.co.uk

It is the policy of OMEGA to comply with all worldwide safety and EMC/EMI regulations that apply. OMEGA is constantly pursuing certification of its products to the European New Approach Directives. OMEGA will add the CE mark to every appropriate device upon certification.

The information contained in this document is believed to be correct, but OMEGA Engineering, Inc. accepts no liability for any errors it contains, and reserves the right to alter specifications without notice. WARNING: These products are not designed for use in, and should not be used for, patient-connected applications.

FL-W7000's INSTALLATION INSTRUCTIONS

This is important information. Read it carefully before beginning work.

- 1) Inspect the meter for damage that may have occured during shipping. If container is damaged report this to the freight carrier immediately.
- Make sure your pressure, temperature, fluid and other requirements are compatible with the meter and components (including O-rings).
- 3) Select a suitable location for installation to prevent excess stress on the meter which may result from:
 - a) Misaligned pipe.
 - b) The weight of related plumbing.
 - c) "Water Hammer" which is most likely to occur when flow is suddenly stopped as with quick closing solenoid operated valves. (If necessary a surge chamber should be installed. This will also be useful in pressure start-up situations.)
- 4) Handle the meter carefully during installation.
- 5) Install the meter vertically with the inlet port at the bottom. No piping runs are required. Because the guide rod extends from the top of the meter during operation, 4" of straight pipe must be provided at the outlet of the meter.
- 6) Meters will support several feet of pipe as long as significant vibration or stress resulting from misaligned pipe are not factors.

INSTALLATION

- FL-W7000 meters are designed for vertical installation only (inlet at bottom, outlet at top).
- The indicator housing is not removeable from the meter tube.
- Do not remove or adjust the screws on the back of the indicator housing. These screws were
 positioned during factory calibration and represent the zero adjustment. If the pointer is set on
 zero proceed with the piping. If the pointer is not set at zero follow these steps.
 - 1) remove front cover of indicator and gasket
 - 2) loosen set screw at base of pointer.shaft
 - 3) reposition pointer to zero line
 - 4) tighten set screw with a 1/16" allen wrenich by holding the pointer shaft and gently tightening the set screw
 - 5) replace gasket and cover of indicator housing

Caution: Zero is factory set when meter is calibrated. Do not loosen nuts that fasten indicator housing to meter body. If indicator housing is moved, the meter will need recalibration.

Maximum Non-Shock Pressure for Flanged Meters

Temperature**

Temp.	Stainles 150# psig		ange Class 600# psig	O-Ring Material EPR Buna-N Viton®	Maximum Temperature 225 °F 275 °F	
200	225	600	1,200	Z alak ^e	350 °F 400 °F	
300 400	200 180	540 . 515	1,100 1,000	Kaireze 400 °F The maximum ambient temperature for the Indicator Housing is 158 °F.		

^{**} Caution: Meters with NPT (threaded) connections can be used in service up to 1500 psi & 400 °F, but always make certain that materials of construction (including O-ring material) are compatible with the fluid to be metered at the desired temperature and pressure.

Viton*, Zalak* and Kalrez* are registered trademarks of E.I. DuPont.

CAUTION:

- O-rings should be replaced if meter is disassembled after it has been in service.
- Do not loosen nuts that fasten indicator housing to metering tube. If the relationship of meter and housing are changed, meter must be recalibrated.
- Serious property damage and great personal injury could occur as the result of a meter used in an unsuitable application.

CLEANING:

Carefully remove the flowmeter from piping system. Remove the threaded inlet and withdraw the float and guide assembly out from the top. (Normally it is not necessary to remove the tapered sleeve or spacers.) All necessary instrument components are now fully accessible for cleaning with a bottle brush and appropriate mild soap solution*. Before the meter is reassembled, inspect all parts for damage. O-rings should be replaced during meter maintenance and cleaning.

To reassemble, carefully guide the magnetic float back into the tube. When installing float/guide assembly make certain that the end of the guide fully engages the inlet and/or outlet float stop. Reinstall and tighten fittings in appropriate ports. Reinstall the instrument into the plumbing system after removing the old teflon tape (with a wire brush) and replacing with fresh tape.


*Do not use cleaning agents that will damage float, tube or O-rings.

CAUTION: Do Not loosen nuts that fasten indicator housing to meter tube. If the relationship of meter and housing are changed, meter must be recalibrated.

WARNING:

Pressure and temperature ratings are based on a study of the engineering data for particular materials used in construction and on the design of Individual models. This information is supplemented by destructive test results. Meters with stainless enclosures must never be operated without shields securely in place. Meters exposed to difficult environments such as those created by certain chemicals, excessive vibration or other stress inducing factors could fail at or below the suggested maximums. Never operate meters above pressure and temperature maximums. It is strongly recommended that all meter installations utilize an appropriate pressure relief valve and/or rupture disc. The pressure settings and locations of these devices should be such that meters cannot be overpressurized. Meter failure could result in damage to equipment and serious personal injury. Always use suitable safety gear, including OSHA approved eye protection when working around meters in service. We are happy to pass along chemical compatibility information that has been published by the manufactures of raw materials used in our products; however, this information Omega Engineering Inc. for a specific should not be construed as a recommendation made by application.

Meters are not specifically recommended for service other than water or air. The user must determine meter sultability for use with other fluids.



METERS FOR GAS SERVICE

Meters used in gas service may be susceptible to float bounce. (This is espcially true in low density gas applications.) To reduce the possibility of float bounce, valves should be installed at both ends of the meter. Make sure there is minimum piping between the valve and the meter body.


During start up (with both valves closed) open the inlet 1/2 turn, then slowly open the outlet two turns. Return to the inlet and open another two turns. Now adjust a combination of the valves to achieve desired flow. Make sure to open the valves slowly. If the float begins to bounce, close the valves immediately and begin procedure again.

Both the inlet and outlet valves should be opened to the minimum required to achieve the desired flow. Follow this procedure during each start up.

A pressure gage installed between the outlet of the meter and the downstream piping will show the pressure in the meter and will allow the exact flow to be calculated by deriving a mulitiplier (x) using the formula shown below.

$$\alpha = \sqrt{\frac{14.7 + \text{operating pressure}}{14.7}}$$

(To use the formula above, multiply the indicated flow by $\boldsymbol{\pi}$ to obtain the actual flow at the corrected pressure.)



WARRANTY/DISCLAIMER

OMEGA ENGINEERING, INC. warrants this unit to be free of defects in materials and workmanship for a period of 13 months from date of purchase. OMEGA's WARRANTY adds an additional one (1) month grace period to the normal one (1) year product warranty to cover handling and shipping time. This ensures that OMEGA's customers receive maximum coverage on each product.

If the unit malfunctions, it must be returned to the factory for evaluation. OMEGA's Customer Service Department will issue an Authorized Return (AR) number immediately upon phone or written request. Upon examination by OMEGA, if the unit is found to be defective, it will be repaired or replaced at no charge. OMEGA's WARRANTY does not apply to defects resulting from any action of the purchaser, including but not limited to mishandling, improper interfacing, operation outside of design limits, improper repair, or unauthorized modification. This WARRANTY is VOID if the unit shows evidence of having been tampered with or shows evidence of having been damaged as a result of excessive corrosion; or current, heat, moisture or vibration; improper specification; misapplication; misuse or other operating conditions outside of OMEGA's control. Components which wear are not warranted, including but not

OMEGA is pleased to offer suggestions on the use of its various products. However, OMEGA neither assumes responsibility for any omissions or errors nor assumes liability for any damages that result from the use of its products in accordance with information provided by OMEGA, either verbal or written. OMEGA warrants only that the parts manufactured by it will be as specified and free of defects. OMEGA MAKES NO OTHER WARRANTIES OR REPRESENTATIONS OF ANY KIND WHATSOEVER, EXPRESS OR IMPLIED, EXCEPT THAT OF TITLE, AND ALL IMPLIED WARRANTIES INCLUDING ANY WARRANTY OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE ARE HEREBY DISCLAIMED. LIMITATION OF LIABILITY: The remedies of purchaser set forth herein are exclusive, and the total liability of OMEGA with respect to this order, whether based on contract, warranty, negligence, indemnification, strict liability or otherwise, shall not exceed the purchase price of the component upon which liability is based. In no event shall OMEGA be liable for consequential, incidental or special damages.

CONDITIONS: Equipment sold by OMEGA is not intended to be used, nor shall it be used: (1) as a "Basic Component" under 10 CFR 21 (NRC), used in or with any nuclear installation or activity; or (2) in medical applications or used on humans. Should any Product(s) be used in or with any nuclear installation or activity, medical application, used on humans, or misused in any way, OMEGA assumes no responsibility as set forth in our basic WARRANTY/DISCLAIMER language, and, additionally, purchaser will indemnify OMEGA and hold OMEGA harmless from any liability or damage whatsoever arising out of the use of the Product(s) in such a manner.

RETURN REQUESTS/INQUIRIES

Direct all warranty and repair requests/inquiries to the OMEGA Customer Service Department. BEFORE RETURNING ANY PRODUCT(S) TO OMEGA, PURCHASER MUST OBTAIN AN AUTHORIZED RETURN (AR) NUMBER FROM OMEGA'S CUSTOMER SERVICE DEPARTMENT (IN ORDER TO AVOID PROCESSING DELAYS). The assigned AR number should then be marked on the outside of the return

The purchaser is responsible for shipping charges, freight, insurance and proper packaging to prevent

FOR WARRANTY RETURNS, please have the following information available BEFORE contacting OMEGA:

- 1. Purchase Order number under which the product was PURCHASED,
- 2. Model and serial number of the product under warranty, and
- 3. Repair instructions and/or specific problems relative to the product.

FOR NON-WARRANTY REPAIRS, consult OMEGA for current repair charges. Have the following information available BEFORE contacting OMEGA:

- 1. Purchase Order number to cover the COST of the repair,
- 2. Model and serial number of the product, and
- 3. Repair instructions and/or specific problems relative to the product.

OMEGA's policy is to make running changes, not model changes, whenever an improvement is possible. This affords our customers the latest in technology and engineering.

OMEGA is a registered trademark of OMEGA ENGINEERING, INC.

© Copyright 1999 OMEGA ENGINEERING, INC. All rights reserved. This document may not be copied, photocopied, reproduced, translated, or reduced to any electronic medium or machine-readable form, in whole or in part, without the prior written consent of OMEGA ENGINEERING, INC.

Where Do I Find Everything I Need for Process Measurement and Control? OMEGA...Of Course!

TEMPERATURE

- Thermocouple, RTD & Thermistor Probes, Connectors, Panels & Assemblies
- Wire: Thermocouple, RTD & Thermistor
- Calibrators & Ice Point References
- Recorders, Controllers & Process Monitors
- Infrared Pyrometers

PRESSURE, STRAIN AND FORCE

- Transducers & Strain Gages
- Load Cells & Pressure Gages
- Displacement Transducers
- ☑ Instrumentation & Accessories

FLOW/LEVEL

- Rotameters, Gas Mass Flowmeters & Flow Computers
- Air Velocity Indicators
- Turbine/Paddlewheel Systems
- ☑ Totalizers & Batch Controllers

pH/CONDUCTIVITY

- pH Electrodes, Testers & Accessories
- Benchtop/Laboratory Meters
- Controllers, Calibrators, Simulators & Pumps
- Industrial pH & Conductivity Equipment

DATA ACQUISITION

- Data Acquisition & Engineering Software
- Communications-Based Acquisition Systems
- Plug-in Cards for Apple, IBM & Compatibles
- Datalogging Systems
- Recorders, Printers & Plotters

HEATERS

- Heating Cable
- Cartridge & Strip Heaters
- Immersion & Band Heaters
- Flexible Heaters
- Laboratory Heaters

ENVIRONMENTAL MONITORING AND CONTROL

- Metering & Control Instrumentation
- Refractometers
- Pumps & Tubing
- Air, Soil & Water Monitors
- Industrial Water & Wastewater Treatment
- pH, Conductivity & Dissolved Oxygen Instruments