

MAX FLOW SIZES FROM 80 TO 500 GPM (300 TO 1800 LPM)

# Flow meters, Flow switches and Flow transmitters

A Large Vane Style For Liquids





NIST Traceable Calibration Certificate Available



These variable-area flow meters have a spring-loaded swinging vane. Mounting is in-line and in any position. Straight pipe runs, before or after the meter, are not required. The all-mechanical sensing system directly drives the pointer, switches and transmitters. This swinging vane can be manually operated with a wrench (factory supplied) to verify or adjust switch points or to free the vane should it become lodged by debris in the fluid.

#### **READOUTS**

The flowmeter has outputs both visual and electronic. Visual displays are either pointer (with inscribed scale) or numeric (digital LCD). Electronic outputs can be mechanical switch closure, 4-20 mA analog, HART or some combination of switches with electronic outputs (for signal redundancy). The switches can be general purpose or rated for hazardous locations (all classes, groups and divisions).



# **CALIBRATION**


All flow meters are individually calibrated for fluids with the viscosity you specify (up to 3000 SSU/660 Centistokes). We also compensate for your fluid's specific gravity. For NIST Traceability please consult factory.

# **CONSTRUCTION MATERIALS**

The meter body, internal moving parts, and seals are offered in a variety of materials to suit a wide range of applications: water, synthetic and petroleum based oils, paint, some corrosives, solvents, air and gases. See selections in the "How to Order" section.


# **LINE CONNECTION**

Ports can be from 1-1/2 to 4 inches. All connections and types are specified in the "How to order" section.



Fluid enters at A, passes around the semi-circular vane B. exits at outlet C. The vane resists the flow because of the spring D. The further the vane is pushed the larger the passageway E becomes. This minimizes pressure drop. The vane shaft turns to operate the pointer F and remote signal devices such as the switch G.

Viton® and Kalrez™ are registered trademark for DuPont Performance Elastomers.



PORT CONN	IECTION			
	Thread	ed Socket-W	eld Max.	Flow
	SAE-St	yle SAE-Sty	le	
	Flange	es Flanges	(GPM)	(LPM)
	(NPT	) (Pipe)	, ,	,
Inches MN	Λ `	, , ,		
1-1/2 38.1	10 = <b>12</b>	= 12W	100	378
2 50.8	30 = <b>16</b>	= 16W	150	567
2-1/2 63.5	50 = <b>20</b>	= 20W	300	1134
3 76.2	20 = <b>24</b>	= 24W	400	1512
4 101	.6 = <b>32</b>	= 32W	500	1890
Flanges are steel; stainless steel units have stainless steel				
flanges. ANS	SI flanges a	also available.		

FLA	NGED				
Ex:	Ex: 24FTCS150RF	= 3" Threaded, (	Carbon Steel Class 150	Raised Fac	e Flange
Pipe	e Size In Inches	Attachment	Material	Class	Style
12	= 1 1/2"	FW=Welded	CS=Carbon Steel	15Ø	<b>RF</b> =Ansi
		FT=Threaded			raised face
16	= 2"		S=316 Stainless	3ØØ	
20	= 2 1/2"				
24	= 3"				
32	= 4"				

# FLUID CHARACTERISTICS

Viscosity number followed by a 'V' (for SSU), 'C' (for centipoise), or 'CS' (for centistokes) followed by the specific gravity. Example: 32V1.Ø would indicate a fluid with a viscosity of 32 SSU with a specific gravity of 1. For dual viscosities (where there is a start up viscosity or where there may be a range) put in both values with a slash. Example: 32Ø/15ØV.9.

32V1.Ø -

# RX1 L-SERVICE Weatherproof (Type 4) Available on all boxes Weatherproof, corrosion proof (Type 4X) Available on all boxes = X

FLOW DIRECTION		
Left to right	=	R
Right to left	=	L
Up	=	U
Down	=	D

#### ST -3ØD

# SPECIAL OPTIONS

High-temp- 400°F std and 300°F for transmitter options	=	HT
Stainless steel ID tag for customer supplied information	=	ST
Safety Glass window ref. page 5	=	TG
Dual spring (required for flows 400gpm or greater)	=	DS

#### **SWITCH SETTING**

= Lowest possible setting No symbol

Desired set point is assumed to be in flow units already selected (GPM). Give flow rate 300 followed by a "D" for flow going down (flow failure) or a "U" for flow going up. Example, 3ØD indicates a setting of 30 GPM in declining flow. Consult factory for settings out of flow range.

### **CONTROL BOX & READOUT**

#### T Box

# "T" Box

"T" box always has a transmitter (4-20 mA) and can be in combination with a mechanical switch for redundancy. It has two junction boxes to separate wiring for switches and transmitters. The display can be analog or digital LCD.

NOTE: The 4-20mA transmitter with or without the LCD and with NO switches is Intrinsically safe with approved barriers.



# LCD readout, 4-20mA with 2 open

CULLECTORS. MA ANAL SCALES OIL FOR 2	
No switches	TXLØ
One SPDT (3 wire)	TXL1
One SPDT (4 wire)	TXL3
One SPDT (3 wire) high temperature	TXL61



#### Pointer, scale and 4-20 mA:

No switches	TXØ
One SPDT (3 wire)	TX1
Two SPDT (3 wire)	TX2
One SPDT (4 wire)	TX3
Two SPDT (4 wire)	TX4
One SPDT (3 wire) high temperature	TX61

# Flow rate display, HART & 4-20mA output:

HART protocol is not intrinsically safe	-
HART & 4-20mA output only	THØ
One SPDT (3 wire)	TH1
Two SPDT (3 wire)	TH2
One SPDT (4 wire)	TH3
Two SPDT (4 wire)	TH4
,	



# "R" Box

"R" box is selected for greater visual resolution.

It holds switches (general purpose and hazardous location all classes, groups and divisions) and transmitters (HART or 4-20 mA). Switch (standard service) and transmitter are offered in this control box together when signal redundancy is desired.

II DOX	
Flow rate display plus:	
Display only	RØ
One SPDT (3 wire)	R1
One high vibration SPDT (3 wire)	R1B
Two SPDT (3 wire)	R2
Two high vibration SPDT (3 wire)	R2B
One SPDT (4 wire)	R3
Two SPDT (4 wire)	R4
One SPDT (3 wire) high temperature	R61
Two SPDT (3 wire) high temperature	R62
One SPDT (3 wire) gold contact	R71
Two SPDT (3 wire) gold contact	R72

### Flow rate display, Hazardous location switches as follows:

One SPDT hazardous location	R7
One DPDT hazardous location	R17
Two SPDT hazardous location	R18
Two DPDT hazardous location	R19

# Flow rate display, 4-20 mA transmitter plus switch options as

Display and transmitter only (Intrinsically safe with no switch options with approved barriers)

One SPDT (3 wire) RX1 Two SPDT (3 wire) RX2 One SPDT (4 wire) RX3 Two SPDT (4 wire) RX4

RXØ

**RX61** 


# Flow rate display, HART & 4-20mA output:

One SPDT (3 wire) high temperature


Hart protocol is not intrinsically safe RHØ HART & 4-20mA output only One SPDT (3 wire) RH1 Two SPDT (3 wire) RH2 One SPDT (4 wire) Two SPDT (4 wire) RH3 RH4

# **CONTROL BOX SELECTION GUIDE**

# STANDARD OFFERING: Control Box "R"



# **SPECIAL OFFERING: Control Box "T"**



# **SPECIAL OPTIONS**

High temperature: (option HT) requires seals of Viton®, EPR, Kalrez™ or Teflon (compatible with fluid). A thermal barrier (heat-resistant cloth) is added between the housing and the control box, which must be used with service option "W" (weatherproof) or "X" (corrosion resistant). A metal scale is provided.

#### Safety Glass window:

(option **TG**) replaces the standard window with "Laminated Safety Glass" ANSI Z97.1 and CPSC 1601 CFR 1201.

# **ENGINEERING DATA**

Maximum fluid temperature: 200 °F (95 °C)

Optional max. fluid temperatures: 300 °F & 400 °F (150 °C & 205 °C) (option HT)

Max. ambient temp: 150 °F (65 °C)


SERIES LN Max. operating pressures (3:1 safety factor): 300 PSI (20.69 BAR)


SERIES LE Max. operating pressures (2:1 safety factor): 500 PSI (34.5 BAR)


Readout accuracy, full scale: ±2 %

# **FLOW & PRESSURE DROP**

Meters with maximum flows to 300 GPM (1200 LPM) impose a pressure drop that increases with flow from 1.9 to 3.8 PSI (avg. 2.2). Flows greater than 400 GPM have a maximum pressure drop of 5.5 PSI.







"Flow up" or "flow down" dimensions are the same. Scale numbers are turned 90° to be right reading. For additional information on flanged connection see page 129.



